

## जल गुणवत्ता जाँच प्रतिवेदन


जल नमूने की फील्ड किट के माध्यम से जाँच करने के पश्चात् विभिन्न परिणामों को निर्धारित प्रपत्र में इन्ट्री किया जाना चाहिए ताकि ये परिणाम आवश्यकता पड़ने पर उपलब्ध करवाया जा सकें। जाँच परिणाम निम्न प्रपत्रों में भरे जा सकते हैं:

### जल गुणवत्ता जाँच प्रपत्र

1. जिला का नाम : शंती
2. ब्लॉक का नाम : बगडू
3. पंचायत का नाम : कुदवागा
4. गाँव का नाम : ॥
5. टोल्न का नाम : ॥
6. निकटवर्ती व्यक्ति का नाम : आदित्य प्रकाश जलान सरस्वती
- जहाँ स्रोत अवस्थित है : शिव विद्या मन्दिर
7. स्रोत का प्रकार : बोरी
8. जल नमूने की जाँच की तिथि : 17/6/2023
9. जल नमूने लेने वाले व्यक्ति का नाम एवं तिथि : मुनेश्वर शंकर  
16/6/2023
10. जल नमूने की जाँच करने वाले व्यक्ति का नाम : रिमी देवी

क्र. सं.	जाँच पैरामीटर का विवरण	पेयजल के लिए निर्धारित सीमा	जाँच परिणाम	टिप्पणी
<b>रसायनिक जाँच</b>				
1	पी.एच.	6.5 - 8.5	7.0	
2	फ्लोराईड	1.5 मिग्रा./ ली.	1.0	
3	नाइट्रेट	45 मिग्रा./ ली.	10	
4	ऑयसन	1.0 मिग्रा./ ली.	0.0	
<b>जीवाणु परीक्षण</b>				
5	ईकोलाई (एच.एस.वायेल)	शून्य (एच.एस.वायेल) का रंग काला नहीं पड़ना चाहिए	0	

परिणाम : उपरोक्त स्रोत का जल पीने योग्य है/ नहीं है।

  
 हस्ताक्षर  
 जल सहिया  
 17/6/2023

हस्ताक्षर  
 जिला समन्वयक  
 (10 & 0)



**Swachh Vidyalaya Puraskar**  
Department of School Education & Literacy  
Ministry of Education, Government of India



**Swachh Bharat**  
**Swachh Vidyalaya**  
A National Mission

# SWACHH VIDYALAYA PURASKAR 2021-22

## District Level Award

This is to certify that **ADITYA PRAKASH JALAN SARASWATI VIDYA MANDIR**.....School  
With UDISE+Code **20142203304**.....has received the District Level Award  
in Swachh Vidyalaya Puraskar 2021-22 and has achieved an overall score of.....**91**.....%  
with a overall rating of .....**★★★★★**.....

*CK Kavi Kanya*

**District Collector**

### Sub Category Wise Self-evaluation Scores

Water.....**86**.....% Toilets.....**79**.....% Handwashing with Soap.....**100**.....% Operation and Maintenance.....**95**.....% Behavior Change and Capacity Building.....**100**.....% COVID-19 Preparedness and response.....**100**.....%

★ Below 35% : Poor | ★★ 35% - 50% : Fair | ★★★ 51% - 74% : Good | ★★★★ 75% - 89% : Very Good | ★★★★★ 90% - 100% : Excellent

Rating Norms

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE**

Nb. 579

Date: 12.10.2020

It is certified that an inspection team headed by Ashish Dey Sarkar,  
Sanitary Inspector (Name of Officers  
with designation) from C. H. C Ratu. (Name of  
Department/Office) inspected the Aditya Prakash Jalan, Saraswati  
Vidya Mandir, Kudlum, Balalong Nagri, Ranchi (Name & Address of  
the School) on 12.10.2020 and found that the Aditya Prakash Jalan  
Saraswati Vidya Mandir, Kudlum, Balalong Nagri (Name of school) has safe  
drinking water facilities for the students and members of staff of the institution and is maintaining  
the hygienic sanitation condition in the school building & the campus as per the norms  
prescribed by the Central/State/U.T Govt.

The above valid for a period of One Year.

Sujeet  
12/10/20

प्रभारी विहितसा पदाधिकारी

Signature with Seal : [Seal]

Name

: Dr. Sujeet Kr. Kashyap.

Designation

: M.O.I.C, C.H.C Ratu  
Ranchi

To

Aditya Prakash Jalan  
Saraswati Vidya Mandir, Kudlum  
Balalong Nagri Ranchi.

(Name & Address of the Institution)